

Oil Field Environmental Incident Summary

Incident: 20150702171925 **Date/Time of Notice:** 07/02/2015 17:19

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: HAMPTON 1-2H

Field Name: UPLAND

Well File #: 21311

Date Incident: 7/2/2015

Time Incident: 16:00

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 96

Sec: 2

Qtr:

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Person: John Breeding
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3.5	Barrels	3.5	Barrels	3.5	barrels
Brine	0.5	Barrels	0.5	Barrels	0.5	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/14/2015

Clean Up Concluded: 7/2/2015

Risk Evaluation:

None

Areal Extent:

120 ft. by 10 ft. area to the East

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Contaminated material was removed and replaced with clean fill.

Wastes Disposal Location: R360

Agencies Involved: Called Jim Potts @ 5:00 pm on 7/2/15

Updates

Date: 7/6/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill remained on location. NDIC retains oversight.